


IMPROVEMENT LOCATION REPORT

SURVEYOR'S NOTE: THIS IS NOT A SURVEY FOR USE BY A PROPERTY OWNER FOR ANY PURPOSE.

LEGEND

- 1/2" REBAR FOUND (OR AS NOTED)
- ⊙ USGLO BRASS CAP MONUMENT FOUND
- FENCE
- ⊕ ELECTRIC METER
- ⊕ NATURAL GAS METER
- ⊕ HATCH COVER
- ⊕ ELECTRIC JUNCTION BOX



C:\WORK\ED PROJECTS\1864 HARRIS TO CHIEPPO\DWG\1864-15-REPTS TO CHIEPPO.DWG, 09 OCT 2014 09:56:14, 5.51, 48

THIS IS TO CERTIFY TO
 The Company: First New Mexico Title & Abstract Company, Inc.
 Title Company: Chicago Title Insurance Company
 That based on File #99023458 Commitment #7605-6-123A provided by First New Mexico Title & Abstract Company, Inc. and survey plat entitled Vera F. Porth Testamentary Trust, prepared by Jeffrey B. Stodler, N.M.P.S. #8327, Job #745, dated 06 October 2000, filed in Cabinet D, Page 133-A of the Taos County Records, an inspection was made under my direction of the subject premises located at #9 Lama Road, El Prado, New Mexico.

I HAVE INSPECTED FOR THE FOLLOWING ITEMS, which, if found, are shown on this drawing:

1. Surface evidence of rights-of-way, old highways or abandoned roads, lanes, trails, driveways and utility lines on or crossing subject premises;
2. Springs, streams, rivers, irrigation ditches, ponds or lakes located on, bordering or crossing subject premises;
3. Evidence of cemeteries or burial grounds located on subject premises;
4. Overhead utility poles, anchors, pedestals, wires or lines overhanging or crossing subject premises and serving other properties;
5. Joint driveways or walkways, joint garages, party walls or rights of support, steps or roofs used in common;
6. Apparent encroachments by buildings, projections or cornices thereof, signs affixed thereto, or any other appurtenances of the subject premises appearing to encroach upon or overhang adjoining properties, or any appurtenances or adjoining properties appearing to encroach upon subject premises, fences or other signs of occupancy, and
7. Specific physical evidence of boundary lines on all sides of subject premises.

This tract is within Zone X, area outside of the 500-year flood boundary as shown on the Flood Insurance Rate Map for Taos County, New Mexico, Community Panel #3505C0790E, dated effective 06 October 2010.

The above information is based on boundary information taken from a prior survey, and may not reflect all information which may be disclosed by a boundary survey. No monuments were set. This tract is subject to all pertinent easements, restrictions and reservations of record, and to exception provisions in the deed in the commitment referenced herein. This report is not to be relied upon for the establishment of fences, buildings or other future improvements.

[Handwritten Signature]

Robert A. Watt, N.M.P.S. 11770 Date 09 October 2014

IMPROVEMENT LOCATION REPORT

Harris to Chieppo

THIS IS NOT A SURVEY PLAT



Red Tail Surveying, Inc.
 Complete Surveying and
 Earth Information Services
 301-A Hilde Street
 Taos, New Mexico 87571-6654
 505-758-7441 800.579.6373
 redtail@redtailsurvey.com

Draftsman: jba
 Proof: Robert A. Watt
 Scale: 1"=30'
 Date: 09 Oct 2014
 Job no. 1864 ILR